

T/T NORTH CAROLINA



SURVEY REPORT FOR "T/T NORTH CAROLINA"

GENERAL				
HAILING PORT:	NOT SIGHTED			
REGISTERED PORT:	NATIONAL VESSEL DOCUMENTATION CENTER			
L.O.A.: 35' 0"	L.W.L.: *	BEAM: 10'6"	DRAFT: 24"	DEPTH: *
GROSS TONS	*		*	
DISPLACEMENT:	7,500 LBS (DRY, REPORTED)		BALLAST: *	
DESIGNER:	INTREPID		BUILDER: INTREPID	
VESSEL USE:	PRIVATE USE ONLY			
NAV. LIMITS:	TO UNDER WRITERS REQUIREMENTS			
VESSELS BERTH:	*		LAID UP: RYBOVICH NORTH	
MASTER:	*			
EXPERIENCE/LICENSE	*			
HULL				CONDITION
TOPSIDES:	MOLDED FIBERGLASS, BLUE			GOOD
BOTTOM:	MOLDED FIBERGLASS, BLACK ANTI-FOULING WITH WHITE BOOT STRIPE			GOOD
SUPERSTRUCTURE:	MOLDED FIBERGLASS, WHITE			GOOD
STEM:	RAKED & FLARED			GOOD
STERN:	TRANSOM			GOOD
FRAMES:	INTEGRAL			GOOD
DECK BEAMS:	INTEGRAL			GOOD
DECKS:	MOLDED FIBERGLASS WITH NONSKID			GOOD
KEEL:	STEPPED			GOOD
SKEG:	*			*
ZINCS:	ON ENGINES			GOOD
THROUGH HULLS:	BRONZE BELOW WATERLINE W/STAINLESS STEEL & PLASTIC ABOVE			GOOD
BILGES FORWARD:	CLEAN AND DRY			GOOD
BILGES AFT:	CLEAN AND DRY			GOOD
BILGES ENG. ROOM	*			*
BULKHEADS:	MOLDED FIBERGLASS			GOOD
STERN RAIL:	FIBERGLASS			GOOD
SELF BAILING CP.	YES			GOOD
WATERTIGHT COMP.:	*			*
STANCHIONS:	*			*
LIFELINES:	RAISED GUNWALES			GOOD
BOW PULPIT:	*			*
BOW SPRIT:	STAINLESS STEEL ANCHOR ROLLER BRACKET			GOOD
DECK HARDWARE:	STAINLESS STEEL			GOOD
SWIM PLATFORM:	FIBERGLASS			GOOD
TRANSOM GATE:	YES, TO PORT			GOOD
OTHER:	*			*
OTHER:	*			*
OTHER:	*			*

SURVEY REPORT FOR "T/T NORTH CAROLINA"

	EXTERIOR	CONDITION
LIVE WELL	*	*
FISH WELL	YES	GOOD
FISH FIGHTING CHAIR	*	*
TACKLE CENTER	YES	GOOD
COCKPIT FREEZER	*	*
FISH BOX ICE MAKER	*	*
GUN-WALE ROD HOLDERS	YES	GOOD
ROCKET TYPE ROD HOLDERS	YES	GOOD
OUTRIGGERS	*	*
SERVICE AIR COMPRESSOR	*	*
DIVE AIR COMPRESSOR	*	*
COCKPIT ENGINE CONTROLS	*	*
WINDSHIELD WIPERS	*	*
WINDSHIELD WASHERS	*	*
FLYBRIDGE REFRIGERATOR	*	*
FLYBRIDGE FREEZER	*	*
FLYBRIDGE ICE-MAKER	*	*
AFT DECK REFRIGERATOR	*	*
AFT DECK FREEZER	*	*
AFT DECK ICE-MAKER	*	*
RADAR ARCH	MOUNTED ON HARD TOP	GOOD
MAST:	LIGHT MAST	GOOD
FENDERS:	FOUR MEDIUM	GOOD
DOCKING LINES:	SIX	GOOD
HARD TOP:	YES	GOOD
BIMINI:	*	*
BIMINI FRAME:	*	*
ENCLOSURE:	*	*
OTHER:	*	*
GROUND TACKLE:	GALVANIZED PLOW TYPE W/ 20' CHAIN & 150' RODE	GOOD
GROUND TACKLE:	SPARE DANFORTH W/ 150' RODE	GOOD
GROUND TACKLE:	ABOVE IS APPROX. LENGTH, RUN OUT & CHECK	GOOD
OTHER:	*	*
ANCHOR WINDLASS:	"MAXWELL" 1000, VERTICAL, ELECTRIC	GOOD
DECK WINCHES:	*	*
DINGHY DAVIT:	*	*
GANGWAY:	*	*
PASSARELLE:	*	*
DINGHY:	*	*
OUTBOARD MOTOR:	*	*
OTHER:	*	*

SURVEY REPORT FOR "T/T NORTH CAROLINA"

ELECTRONICS			CONDITION
	LOWER STATION	TOWER	
COMPASS:	4" RITCHIE	*	GOOD
AUTOPILOT:	SIMRAD AP26	*	GOOD
RADAR:	RAYMARINE	*	GOOD
AIS:	*	*	*
GPS.:	RAYMARINE E120	*	GOOD
GPS:	*	*	*
CHART PLOTTER:	IN ABOVE GPS'S	*	GOOD
CHART PLOTTER	*	*	*
VHF:	ICOM IC-M506	*	GOOD
VHF:	ICOM IC-M504	*	GOOD
HANDHELD VHF'S:	*	*	*
SSB:	*	*	*
HAILER:	*	*	*
CELL PHONE	*	*	*
SAT. PHONE:	*	*	*
FISHFINDER:	*	*	*
DEPTH FINDER:	IN ABOVE GPS & HAWKEYE DEPTH	*	GOOD
SONAR:	RAYMARINE CP370	*	GOOD
SPEED LOG:	IN ABOVE GPS	*	GOOD
SW. TEMP. GAUGE:	*	*	*
WIND METER:	*	*	*
COMPUTER:	*		*
LAP TOP:	*		*
SOFTWARE:	*		*
OTHER:	*		*
FAX, PRINTER ETC.	*		*
TV. VCR. DVD	SHARP TV IN CABIN		GOOD
TV. VCR. DVD	*		*
TV. VCR. DVD	*		*
TV. VCR. DVD	*		*
TV. VCR. DVD	*		*
OTHER:	*		*
SAT. TV.	*		*
STEREO:	FUSION IPOD/SAT/TUNER AT HELM STATION		GOOD
STEREO:	*		*
STEREO:	*		*
OTHER:	*		*
OTHER:	*		*

SURVEY REPORT FOR "T/T NORTH CAROLINA"

FIRE FIGHTING & SAFETY GEAR		CONDITION
HAND EXT'SHER	ONE, 2.5 LB DRY POWDER	PURCHASE
INSPECTION DATE:	EXPIRED	SERVICE
BUILT IN SYSTEM	*	*
LOCATION:	*	*
INSPECTION DATE:	*	*
MANUAL RELEASE:	*	*
AUTOMATIC RELEASE:	*	*
REMOTE INDICATOR:	*	*
SHUT-DOWNS:	*	*
AUX. FIRE PUMP:	DECK WASH DOWNS	GOOD
MANUAL BILGE P/PS	*	*
EL. BILGE PUMPS	YES, SUBMERSIBLE TYPE	GOOD
ENG. DRIVEN P/PS	*	*
BILGE ALARMS	YES	GOOD
LIFE JACKETS, TYPE "I":	*	*
LIFE JACKETS, TYPE "II"	FOUR	GOOD
LIFE JACKETS, OTHER	TWELVE INFLATABLE TYPE	GOOD
THROW CUSHIONS:	*	*
LIFE RINGS:	ONE RING	GOOD
LIFE RAFTS:	*	*
INSPECTION DATE:	*	*
FLARES, RED HAND HELD:	THREE	GOOD
DATE OF EXPIRY:	FEBRUARY 2021	GOOD
FLARES, ORANGE H-HELD:	*	*
DATE OF EXPIRY:	*	*
FLARES, CARTRIDGES:	*	*
DATE OF EXPIRY:	*	*
EPIRB:	*	*
FIRST AID KIT:	YES	GOOD
U.S.C.G. NOTICES	YES	GOOD
FIRE DETECTORS:	*	*
SMOKE DETECTORS:	*	*
FUME DETECTORS:	*	*
BELL:	*	*
HORN:	YES	GOOD
RULES OF THE ROAD BOOK	YES	GOOD
RUNNING LIGHTS:	ALL WORKING	GOOD
ANCHOR LIGHTS:	WORKING	GOOD
SEARCHLIGHTS:	YES, "ACR"	GOOD
SPREADER LIGHTS:	*	*
OTHER:	*	*

SURVEY REPORT FOR "T/T NORTH CAROLINA"

MACHINERY		CONDITION	
NO ENGINE SURVEY WAS REQUESTED OR PERFORMED BY THIS SURVEYOR			
ENGINE LOCATION:	MOUNTED ON TRANSOM	GOOD	
NUMBER & TYPE:	TWO, GASOLINE	GOOD	
MAKE:	SUZUKI	GOOD	
PORT MODEL #:	DF 300 AP	GOOD	
STBD. MODEL #:	DF 300 AP	GOOD	
PORT SERIAL #:	30002P-611224	GOOD	
STBD. SERIAL #:	NOT SIGHTED	GOOD	
ENGINE HOURS:	PORT: 857	STBD.: 856	N/A
H.P.:	300 EACH	GOOD	
R.P.M.	5000 – 6000	GOOD	
# CYLINDERS:	EIGHT	GOOD	
CRUISE SPEED:	30 KNOTS	GOOD	
MAX. SPEED:	35 KNOTS	GOOD	
WHEN O/HAULED:	NOT REPORTED	N/A	
ALARM SYSTEMS:	YES	GOOD	
ENGINE BED:	TRANSOM MOUNTED	GOOD	
PAN UNDER ENGINE:	*	*	
COOLING SYSTEM:	SALT WATER	GOOD	
VENTILATION:	ADEQUATE	GOOD	
FUEL PUMP:	ELECTRICAL	GOOD	
FILTERS:	SINGLE SUZUKI BOWLS IN-LINE WITH BOWL ON ENGINES	GOOD	
EXHAUST LINE:	THROUGH LOWER UNIT	GOOD	
EXHAUST MUFFLER:	*	*	
SYNCHRONIZER:	*	*	
CONTROLS:	SINGLE LEVER ELECTRONIC	GOOD	
SHAFT LOG TYPE:	*	*	
BEARINGS:	*	*	
STUFFING BOX:	*	*	
PROPELLERS:	THREE BLADE STAINLESS STEEL, 16" x 18" + TWO SPARES	GOOD	
PROPELLER SHAFTS	STAINLESS STEEL, INTERNAL	GOOD	
STRUTS:	*	*	
STRUT BEARINGS:	*	*	
PROP: PROTECTION	HULL, KEEL & LOWER UNIT SKEG	GOOD	
RUDDER	OUTBOARD ENGINES	GOOD	
RUDDER STUFF BOX	*	*	
TRIM TABS:	STAINLESS STEEL, DOUBLE RAM, 15.5" x 10.5"	GOOD	
BOWTHRUSTER:	"VETUS", ELECTRIC, SIX BLADE PROPELLOR IN 6" TUBE	GOOD	
OTHER:	*	*	
STABILIZERS:	*	*	

SURVEY REPORT FOR "T/T NORTH CAROLINA"

TRANSMISSIONS		CONDITION
TYPE:	*	*
MODEL:	*	*
REDUCTION RATIO:	*	*
PORT SERIAL #:	*	*
STBD. SERIAL #:	*	*
TROLLING VALVES:	*	*
STERN OR VEE DRIVES		CONDITION
TYPE:	*	*
MODEL:	*	*
PORT SERIAL #:	*	*
STBD. SERIAL #:	*	*

GENERATORS			CONDITION
AUX. GENERATOR:	KOLHER	12.9 HOURS	* GOOD
LOCATION:	AFT BELOW COCKPIT SOLE		* GOOD
MODEL #:	NOT SIGHTED		* N/A
SERIAL #:	NOT SIGHTED		* N/A
KILOWATTS:	NOT SIGHTED		* N/A
VOLTAGE:	120/240		* GOOD
NO. CYLINDERS:	THREE		* GOOD
R.P.M.	1800		* GOOD
COOLING SYSTEM:	FRESH WATER		* GOOD
OTHER:	*	*	* *
OTHER:	*	*	* *

TRIAL RUN DATA:											
	PORT ENGINE:				STARBOARD ENGINE:						SPEED
	R.P.M.	WATER TEMP.	OIL PRESS	DRIVE OIL	R.P.M.	WATER TEMP.	OIL PRESS.	DRIVE OIL	% LOAD	GPH PER ENG	FROM GPS IN KNOTS
SLOW	*	*	*	*	*	*	*	*	*	*	*
CRUISE	*	*	*	*	*	*	*	*	*	*	*
CRUISE	*	*	*	*	*	*	*	*	*	*	*
CRUISE	*	*	*	*	*	*	*	*	*	*	*
FULL	*	*	*	*	*	*	*	*	*	*	*
NO SEA TRIAL WAS REQUESTED OR PERFORMED BY THIS SURVEYOR											
*											
*											

SURVEY REPORT FOR "T/T NORTH CAROLINA"

ELECTRICAL		CONDITION
12 VOLT CHARGER	36 AMP PRO MARINER	GOOD
12 VOLT CHARGER	*	*
24 VOLT CHARGER	*	*
24 VOLT CHARGER	*	*
32 VOLT CHARGER	*	*
DC. CONVERTER	*	*
INVERTER:	1500 WATT, COTEK	GOOD
INVERTER CHARGER:	*	*
SHORE TRANSFORMERS	*	*
BATTERY INSTALLATION	THREE x 12 VOLT BELOW HELM	GOOD
BATTERY INSTALLATION	*	*
BATTERY INSTALLATION	*	*
BATTERY INSTALLATION	*	*
BATTERY SWITCHES	THREE, APPROVED TYPE	GOOD
DRIP PANS	PLASTIC BOXES WITH LIDS, SECURE	GOOD
CABLE & TERMINAL CONNECTS.	SOUND & SECURE	GOOD
LIGHTS	12 VOLT DC	GOOD
WIRING	THERMOPLASTIC WHERE SIGHTED	GOOD
125 VOLT SHORE RECEPTACLES	*	*
250 VOLT SHORE RECEPTACLES	*	*
PHONE / TV RECEPTACLES	*	*
30 AMP CABLES	*	*
50 AMP CABLES	*	*
100 AMP CABLES	*	*
PIG TALES	*	*
AC. SWITCHBOARD	*	*
DC. SWITCHBOARD	AT HELM	GOOD
CIRCUIT BREAKERS	YES	GOOD
LIGHTNING ARRESTER	BONDING SYSTEM	GOOD
OTHER:	*	*
OTHER:	*	*
AIR CONDITIONING SYSTEM	*	*
REVERSE CYCLE HEATING	*	*
OTHER	*	*
STEERING GEAR	HYDRAULIC/ELECTRIC	GOOD

SURVEY REPORT FOR "T/T NORTH CAROLINA"

WATER TANKS		CONDITION
NO. & CAPACITY	ONE, 40 GALLONS, REPORTED	GOOD
SHAPE	RECTANGULAR	GOOD
MATERIALS	POLY PLASTIC	GOOD
LOCATION	BELOW DECK, CENTERLINE FORWARD	GOOD
LOCATION	*	*

FUEL TANKS		CONDITION
NO. & CAPACITY	ONE, 258 GALLONS, REPORTED	GOOD
SHAPE	RECTANGULAR	GOOD
MATERIALS	ALUMINUM	GOOD
SECURED	YES	GOOD
BONDED	YES	GOOD
LOCATION	BELOW COCKPIT SOLE	GOOD
LOCATION	*	*
LOCATION	*	*
LOCATION	*	*
FILLING LINES	HOSE	GOOD
VALVES	BRONZE	GOOD
LOCATION	AT TANK & FILTERS	GOOD
VALVE ACCESSIBILITY	GOOD	GOOD
INFLAMMABLES CARRIED	*	*

OIL & GASOLINE		CONDITION
CLEAN ENGINE OIL	*	*
LOCATION	*	*
CLEAN HYDRAULIC OIL	*	*
LOCATION	*	*
DIRTY OIL	*	*
LOCATION	*	*
GASOLINE	*	*
LOCATION	*	*

HOLDING TANKS & TREATMENT SYSTEMS		CONDITION
BLACK WATER TANK	YES	GOOD
LOCATION	NOT SIGHTED	GOOD
BLACK WATER TANK	*	*
LOCATION	*	*
GRAY WATER TANK	SUMPS	GOOD
LOCATION	IN BILGE BELOW CABIN SOLE	GOOD

SURVEY REPORT FOR "T/T NORTH CAROLINA"

INTERIOR		CONDITION
NO. OF CABINS	ONE	GOOD
ENCLOSED HEADS	ONE	GOOD
INTERIOR FINISH	MOLDED FIBERGLASS	GOOD
CABIN SOLE	MOLDED FIBERGLASS	GOOD
RUGS, CARPETING	*	*
TRIM	MOLDED FIBERGLASS	GOOD
OVERHEAD	AS ABOVE	GOOD
DINETTE	*	*
BUNK CUSHIONS	*	*
CURTAINS	*	*
OTHER	*	*
GALLEY		CONDITION
LOCATION	IN CABIN	GOOD
STOVE	*	*
OVEN	*	*
STOVE TOP	SINGLE BURNER "KENYON"	GOOD
STOVE SHUT OFF'S	*	*
BBQ	*	*
MICROWAVE	YES	GOOD
CONVECTION OVEN	*	*
VENTILATION	ADEQUATE	GOOD
REFRIGERATOR	YES "ISOTHERM"	GOOD
FREEZER	COMPARTMENT IN ABOVE	GOOD
OTHER REFRIGERATION	*	*
OTHER REFRIGERATION	*	*
ICE-MAKER	*	*
SMALL APPLIANCES	*	*
CENTRAL VACUUM SYSTEM	*	*
HOT WATER HEATER	*	*
INSTANT WATER HEATER	*	*
AIR CONDITIONING	MARINE AIR	GOOD
WASHER / DRYER	*	*
DISHWASHER	*	*
COMPACTOR	*	*
GALLEY COUNTER	*	*
SHOWER	ONE + DECK WASHDOWN	GOOD
TUB'S	*	*
JACUZZI'S	*	*
OTHER	*	*
OTHER	*	*